

## ThunderMaster2 Release Note (2025/02/21)

### V4.17

- Add “Windows Dynamic Lighting Control” and its tooltips.  
When implementing WDLC, users need to follow below rules:
  1. Windows 11 、 OS 22H2.2361 and above.
  2. MCU FW v2.5 and above.
  3. Install “High Performance Graphics Card Device” driver. (Already integrate into ThunderMaster driver)
  4. ThunderMaster v4.17 and above.
- Add default fan pictures.
- Add the 3<sup>rd</sup> fan control. (RTX 5090 only)
- Change fan control sequence.
- Update NVAPI R570.
- Update FrameView API v1.5
- Fix bug

### V4.16

- Fix fan curve storage issue.
- Fix user defined fan curve issue under single fan condition.

### V4.15

- Add font adjustment function.
- UI optimization.
- Fix “SUPER” series model name too long error.
- Fix Win11 recognition error.

### V4.14

- Add RGB Control – Rainbow light intensity and speed can be adjusted.
- Support RGB Control – white LED.
- Fix minor issue.
- Update SaVBIOS.
- Update NVAPI R525.

### V4.13

- Add RGB Control – “GPU Temperature” setting points can be adjusted.

### V4.12

- Add “ONE TWO SYNC” function
- Optimize UI operation
- Update “tool-tips”
- Fix minor issue

### V4.11

- Adding new ARGB LED lighting effect (need to upgrade on-board MCU F/W)

### V4.10

- Fix “set to default” issue, RTX 20 series and RTX 30 GamingPro series
- Fix minor issue

#### V4.9

- Fix “User defined fan curve” issue
- Update multi-language for “tool-tips”
- Fix minor issue

#### V4.8

- Fix LED “GPU Temperature” issue
- Fix some bugs

#### V4.7

- Fix some bugs

#### V4.6

- Adding “FanStop ON/OFF” feature under “User Defined Fan Curve”
- Fix some bugs

#### V4.5

- Adding “Change Screen Size” feature
- Adding “Saving LED Control to Board” feature
- Fix some bugs

#### V4.4

- Fix “Frame Rate Target can not change issue”
- Fix “OC memory, STATUS GPU display error issue”
- Remove “F/W upgrade available”

#### V4.3

- “OC SCAN” bug fixed
- Some minor bugs fixed

#### V4.21

- Adding multiple language support

#### V4.2

- Added RTX 30 series support

#### V4.1

- Added “disable warning message option 75C+0RPM and 85C”
- Default “profile 1”